


CORNER RECORD

Document Number 9

City of So. Lake Tahoe

County of El Dorado, California

Brief Legal Description Lot 2 Gardner Mountain No. \* 5 SD B-63  
S.S., T12N, R18E, MDM.



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 9/25/2000

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See pg. 2

A description of the physical condition of the monument as found and as set or reset:


See pg. 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 10/3 2000

Signed Ronald W. Turner P.L.S or R.C.E. No. 4029



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 18, 2000

and examined and filed JAN 11, 2001

Signed [Signature] P.L.S or R.C.E. No. 5084

Title Assoc Land Surveyor

County Surveyor's Comment \_\_\_\_\_



APN 23-692-02

12-18-05 SWH

DA 259

