


CORNER RECORD

Document Number 7City of So. Lake TahoeCounty of El Dorado, CaliforniaBrief Legal Description Lot 12, Blk. 20, Tahoe Sierra No. 3, A-45:46

S.3

T12N

R18E

M.D.M.

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey June 30, 2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See pg. 2

A description of the physical condition of the monument as found and as set or reset:

See pg. 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 12-1-2000

Signed Ronald W. Turner L.S. or R.C.E. No. 4029

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 18, 2000and examined and filed JAN 11, 2001Signed Richard L. Briner P.L.S. or R.C.E. No. 5084Title ASSOC. LAND SURVEYOR

County Surveyor's Comment _____

